


3200-4585 KytKentäohje
3200-4585 Wiring instructions



- 1 Kierroslukumittari (W)
- 2 B(+) Akku
- 3 Merkkivalo (D+)
- 4 B(-) Akku, maa

- 1 Tachometer (W)
- 2 (B+) Battery
- 3 Indication lamp (D+)
- 4 (B-) Battery, GND